I hereby certify that this correspondence is being deposited with the United States Postal Service as First Class Mail In an envelope addressed to the Commissioner for Patents, P.O. Box 1450, Alexandria VA. 22313-1450.

By Ruist O'Cone (on /30/2007)
Name
Date

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Patent No.: 7,107,503 Atty Docket: 10010880-1

Issued:

September 12, 2006 Balzer

Inventor(s):

BOUNDARY SCAN WITH GROUND BOUNCE RECOVERY REQUEST FOR ISSUANCE OF CERTIFICATE OF CORRECTION

Attn: Certificate of Correction Branch Commissioner for Patents P.O. Box 1450 Alexandria VA 22313-1450

Sir:

Agilent Technologies, Inc., assignee of the entire interest in the above-identified patent, respectfully requests that a Certificate of Correction be issued in accordance with 37 C.F.R. 1,322 and/or 1 323

Enclosed herewith is a completed copy of Form PTO/SB/44 describing the various errors involved in the above-identified patent.

- The errors are a result of USPTO mistake. NO FEE is required.
- 2. A The errors are a result of Applicant's mistake. \$100 Fee required.
- 3. The errors are a result of both USPTO and Applicant's mistakes. \$100 Fee required.

If boxes 2 or 3 above are checked, please charge the \$100.00 fee as set forth in 1.20(a), for Applicant's errors (37 C.F.R. 1.323), to our Deposit Account 50-1078. A duplicate copy of this letter is enclosed. Issuance of a Certificate of Correction to correct these errors, which occurred in good faith is therefore respectfully requested. We shall appreciate your returning to us an executed copy of this Certificate of Correction for attachment to our Letters Patent.

Respectfully submitted,

Cynthia S. Mitchell

AGILENT TECHNOLOGIES, INC. Legal Department, DL 429 Intellectual Property Administration P.O. Box 7599 Loveland, Colorado 80537-0599 Phone No. (970)679-3238 U.S. Patent and Trademark Office; U.S. DEPARTMENT OF COMMERCE
Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.
(Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

Page 1	of 1

PATENT NO. : 7,107,503

APPLICATION NO.: 10/078,883

ISSUE DATE : September 12, 2006

INVENTOR(S) : Balzer

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In column 11, line 29, in Claim 10, delete "update" and insert - - UPDATE - -, therefor,

In column 12, line 4, in Claim 17, delete "update" and insert -- UPDATE --, therefor.

MAILING ADDRESS OF SENDER (Please do not use customer number below): Agilent Technologies

This collection of information is required by 37 CPR 1.322, 1.322, and 1.324. The information is required to obtain or retain a benefit by the called which is to life only by the USFO to procease) an application. Confidentiality is governed by 59 USF. 0.21 call 427 CFR 1.4. This collection is estimated to take 1.6 hour to complete, including gathering, preparing, and submitting the completed application form to the USFTO. Time will very depending upon the individual case. Any commands on the summer of time by current to complete the form and/or supportance for reducing this benefit subserts, south to the Chile information Officer.

FORUS TO THIS ADDRESS, SERIO TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandris, VA 22331-4450.